


DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 11/21/2013
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 50A261	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/21/2013
NAME OF PROVIDER OR SUPPLIER YAKIMA VALLEY SCHOOL		STREET ADDRESS, CITY, STATE, ZIP CODE 609 SPEYERS ROAD SELAH, WA 98942		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	<p>INITIAL COMMENTS</p> <p>This report is a result of an unannounced Federal Life Safety re-certification survey conducted at Yakima Valley School located at 609 Speyers Road, Selah, WA on November 21, 2013 by staff from the Washington State Patrol, Fire Protection Bureau, Union Gap Detachment. This inspection was conducted in cooperation with the Survey Team from the Washington State Department of Social and Health Services (DSHS).</p> <p>The 2000 existing edition of the Life Safety Code was utilized for the survey in accordance to 42 CFR 483.70: Requirements for Long Term Care.</p> <p>The Long Term Care 128 bed facility, census of 76 was provided by the Interim Superintendent and verified by Director of Nursing. The facility consists of 7 cottages with 2 units in each of type V-1 hour construction. Each cottage has a partial basement that is used for mechanical services of the building only. Each cottage is fully sprinkled with an automatic fire alarm system in place. Exit discharge points are to grade have been provided with an all weather surface and lead to a public way.</p> <p>The facility is in substantial compliance with the Life Safety Code 2000 Edition as adopted by C.M.S.</p> <p>The Surveyor was:  Deputy State Fire Marshal Nursing Home Surveyor 28058</p> <p>The Surveyor was from: Washington State Patrol</p>	K 000		

RECEIVED
DEC 02 2013
FIRE PROTECTION
BUREAU

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE


(X6) DATE

Jill Simmel - McPherson, Interim Superintendent 11-21-13

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 11/21/2013
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 50A261	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/21/2013
NAME OF PROVIDER OR SUPPLIER YAKIMA VALLEY SCHOOL			STREET ADDRESS, CITY, STATE, ZIP CODE 609 SPEYERS ROAD SELAH, WA 98942		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	Continued From page 1 Fire Protection Bureau 2715 Rudkin Road Union Gap, WA. 98903-1795 Telephone: (509) 575-2190 FAX: (509) 576-3002  28058	K 000			

RECEIVED
DEC 02 2013
FIRE PROTECTION
BUREAU